



Certificate CA96/157.00
The management system of

The PIC Group Limited

111 Simcoe St. N., 2nd Floor
Oshawa, Ontario L1G 4S4, Canada

has been assessed and certified as meeting the requirements of

ISO 9001:2015

For the following activities:

The design, development and provisions for training programs, and materials for quality related public seminars and in-house training courses. The provisions for quality related inspection, engineering, consulting and training resource services.

Further clarifications regarding the scope of this certificate and the applicability of ISO 9001:2015 requirements may be obtained by consulting the organization

This certificate is valid from 30 August 2015 until 30 August 2018 and remains valid subject to satisfactory surveillance audits. Recertification audit due a minimum of 60 days before the expiration date. Issue 8 : 16 August 2017. Certified since January 1996.

The audit leading to this certificate commenced on 11/05/2017. Previous issue certificate validity date was until 30/08/2018.

This is a multi-site certification. Additional site details are listed on subsequent pages.

Authorized by:

Ralph McLouth
Vice President of Accreditation, North America
SGS North America, Inc.
201 Route 17 North, Rutherford, NJ 07070, USA
t (201) 508-3000 f (201) 935-4555 www.us.sgs.com

This certificate remains the property of SGS and shall be returned upon request

Page 1 of 2



This document is issued by the Company subject to its General Conditions of Certification Services accessible at www.sgs.com/terms_and_conditions.htm. Attention is drawn to the limitations of liability, indemnification and jurisdictional issues established therein. The authenticity of this document may be verified at <http://www.sgs.com/en/certified-clients-and-products/certified-client-directory>. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.



The PIC Group Limited

ISO 9001:2015

Issue 8 : 16 August 2017



Additional facilities

202 South Blair St., Whitby, ON L1N 8X9, Canada

Scope: The provisions for quality related inspection, engineering, consulting and training resource services.

104 Dawson Road, Guelph, ON N1H 1A7, Canada

Scope: The provisions for quality related inspection, engineering, consulting and training resource services.

200 Universal Road, Unit 1, Woodstock, ON N4S 7W3, Canada

Scope: The provisions for quality related inspection, engineering, consulting and training resource services.

1303 McDougall Avenue, Windsor, ON N8X 3M6, Canada

Scope: The provisions for quality related inspection, engineering, consulting and training resource services.

**PIC QUALITY SOLUTIONS , S.A. DE C.V., Av. Sierra Leona No. 360
PISO #9 Fraccionamiento Villa Antigua, San Luis Polosi, S. L. P.
78214, Mexico**

Scope: The provisions for quality related inspection, engineering, consulting and training resource services.

**The PIC Group Inc., 50459 Central Industrial Drive
Shelby Township, MI 48315, United States**

Scope: The provisions for quality related inspection, engineering, consulting and training resource services.

